andis®

MODEL BGC CLIPPER
120 VOLT



ITEM NO.	PART NO.	DESCRIPTION	QTY. REQ'D
1		Drive Cap	
1a	65266	Drive Cap (Red)	1
1b	65267	Drive Cap (Black)	1
2		Upper Housing	
2a	22963	Upper Housing (EXCEL) - Red	1
2b	22966	Upper Housing (TrendSetter) - Black	1
3	27198	Motor Frame Clip	1
4	65828	Screw	1
5	22682	Switch & Circuit Board Assembly	1
6	27352	Magnetized Field Assembly	1
7	65805	Brush Retaining Clip	
8	64965	Insulator	1
9		Hanger Bail	
9a	22267	(for units after 7/3/03)	1
9b	25061	(for units before 7/3/03)	1
10	64945	Rear Motor Frame	1
11		Lower Housing	
11a	65284	Lower Housing (UL) Red	1
11b	65279	Lower Housing (UL) Black	1
12	64606	Front Housing Screw	1
13		Hinge Assembly	
13a	S21743	Hnge Assy (BGC & Oster 76 & 89)	1
13b	S27091	Hnge Assy (BGC & Oster 10,22,111)	1
14	27861	Blade Hinge Screw	1
15	27847	Carbon Brush With Shunt	1

ITEM NO.	PART NO.	DESCRIPTION	QTY. REQ'D
16	64003	Blade Bracket	2
17	64139	Blade Screw	1
18	64027	Blade Guide	1
19	64013	Tension Spring	1
20	21977	Armature Assembly (Includes	2
21	27854	Cam & Bearing Assembly	2
22	21068	Large Bearing Cup	1
23	65013	Front Motor Frame	2
24	22319	Blade Drive Assembly	1
25	15766	Blade Drive Screw	1
26	22086	Rear Housing Screw	
27	26049	Cord Set	1
28	21067	Small Bearing Cup	1
29	65806	Brush Spring	
30	64991	Oil Seal	1
31	17091	Self-Adhesive Foam Pad	1
32	22909	Blade Retaining Spring	

IMPORTANT INFORMATION

When ordering repair parts, include part number, part name and model of trimmer. For best performance, trimmer blades should be CLEANED and OILED with Andis Clipper Oil before and after use, If repair is necessary, return to any Andis Authorized Repair Service Station, or to Andis Company, 1800 Renaissance Blvd., Sturtevant, Wisconsin, 53177 U.S.A.. Pack carefully, mail either Insured Parcel Post, or U.P.S. , attach a letter to outside of package explaining difficulty.

Rev-D 2-14-06